



type : 13 BMA-50-0-13

	date	sign
drawn	05.04.00	4726/Bom
checked	11.04.00	1778 / TWS
approved	11.04.00	1778 / TWS



scale
5 : 1



dimensions in mm



HUBER + SUHNER RFX

OZ drawing :

drawing number
3.13.32746_1

index
a